



3D VIEW - CORE LOCATIONS



SUMMARY:

GPR scanning was conducted within the proposed scanning area. The survey did not identify any potential conduit within the scanned area.

Based on the GPR results, ideal coring locations were identified and marked in both the 3D and 2D views for reference.

IMPORTANT:
THIS DRAWING IS BASED ON GPR DATA AND SHOULD BE USED FOR INFORMATIONAL PURPOSES ONLY.
ACTUAL CONDITION MAY VARY.
NOT FOR CONSTRUCTION.

STONE CONCRETE
CUTTING & CORING

PROJECT: GPR SCANNING - REBAR & STEEL PLATE LAYOUT

	MM/DD/YY	
1	26 /07 /2026	
2		
3		
4		
5		

01
A